Release news TRUCKS Release 2024.00

In this release you will get several helpful and smooth functions in the software. One is that you will find information about the limited functionalities that occur if the software turns invalid.

Another helpful function is the new information bar in the software. It will get new icons for the battery status, for showing the connection status, and one that tell if you have any news to read. In the information bar you will also find a new button to the Secure Gateway Portal login. You can also see if any of your colleagues is logged in to the portal.

Besides these helpful functionalities, there will also be a lot of ADAS calibration updates and service-related functions. Adjustments has been added on both trucks, buses, light commercial vehicles, and trailer.

You will find a lot of updates on new and old vehicles, on several different brands, models, and systems. Some examples will be the new DAF XD and Scania Bus C-series.

Find more detailed information about updated models below.

autocom

DAF

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
XF [13-17]	Year model updated	2013-2017								●					
	Read data from ECU and save data to file	2013-2017								●					
	Write data to ECU from file	2013-2017								●					
CF [13-17]	Year model updated	2013-2017								●					
	Read data from ECU and save data to file	2013-2017								●					
	Write data to ECU from file	2013-2017								●					
LF	Year model updated	2022-2023	●	●	●			●		●	●		●		●
	Adblue tank heater relay	2022-2023	●												
	AEBS event counter	2022-2023													●
	AEBS Event counters reset	2022-2023													●
	Calibration camera	2022-2023													●
	Calibration radar	2022-2023													●
	Cleaned diesel particulate filter installation	2022-2023	●												
	Cylinder deactivation	2022-2023	●												
	Deactivate service alert system	2022-2023									●				
	ECU reset	2022-2023								●					
	Fuel system leakage test	2022-2023	●												
	Glowplug relay	2022-2023	●												
	Key programming	2022-2023						●							
	Level sensor calibration	2022-2023											●		
	Loudspeaker test	2022-2023													●
	Mute	2022-2023													●
	New diesel particulate filter installation	2022-2023	●												
	Number of programmed keys	2022-2023						●							
	Read service parameters	2022-2023								●	●				
	Regeneration	2022-2023	●												
	Remote controls programming	2022-2023						●							
	Service information	2022-2023													●
	Status indication	2022-2023													●
	Variable geometry turbocharger electronic actuator installation	2022-2023	●												
	Vehicle preset max speed	2022-2023	●												
	VSC calibration	2022-2023		●											
	Write new service parameters, range/date	2022-2023								●	●				
XF [22-]	Year model updated	2022-2023	●							●	●			●	●
	(Customer specific) Speed limit modification	2022-2023								●					
	Activate brake lights	2022-2023								●					
	Activate fog light	2022-2023								●					
	Activate headlight left	2022-2023								●					
	Activate headlight right	2022-2023								●					
	Activate rear light	2022-2023								●					
	Calibration camera	2022-2023													●
	Change set values for tire pressure	2022-2023												●	
	Cleaned diesel particulate filter installation	2022-2023	●												
	Next service	2022-2023									●				
	Rear differential lock solenoid	2022-2023								●					
XG / XG+	Year model updated	2022-2023	●							●	●			●	●
	(Customer specific) Speed limit modification	2022-2023								●					
	Activate brake lights	2022-2023								●					
	Activate fog light	2022-2023								●					
	Activate headlight left	2022-2023								●					
	Activate headlight right	2022-2023								●					
	Activate rear light	2022-2023								●					
	Calibration camera	2022-2023													●
	Change set values for tire pressure	2022-2023												●	
	Cleaned diesel particulate filter installation	2022-2023	●												
	Next service	2022-2023									●				
	Rear differential lock solenoid	2022-2023								●					
XD	Year model updated	2023	●	●	●	●	●	●	●	●	●		●	●	●
	(Customer specific) Speed limit modification	2023								●					
	ABS valve front left	2023		●											
	ABS valve front right	2023		●											
	Accelerated clutch adaption	2023					●								
	Accelerator pedal calibration	2023	●												
	Activate air shut off valve	2023	●												
	Activate brake lights	2023								●					
	Activate fog light	2023								●					
	Activate headlight left	2023								●					
	Activate headlight right	2023								●					
	Activate heater	2023								●					
	Activate rear light	2023								●					
	Activate the fuel dosing valve	2023	●												
	Activate the tank heater valve for AdBlue	2023	●												
	Actuator test of turbo charger	2023	●												
	Adaptation for battery replacement	2023								●					
	Adblue pump module prime test	2023	●												
	AEBS event counter	2023													●
	AEBS Event counters reset	2023													●
	Calibration camera	2023													●
	Calibration radar	2023													●
	Change set values for tire pressure	2023												●	
	Check delivery to the fuel dosing valve	2023	●												
	Check if common rail pressure release valve is stuck in closed position	2023	●												
	Check injection system during cranking	2023	●												
	Check of Accelerator Pedal Sensor	2023	●												
	Check the fuel dosing valve for leakage	2023	●												
	Check the high pressure fuel system for leakage after a repair	2023	●												
	Check wheel sensor battery	2023												●	
	Checking the cooling fan clutch	2023	●												
	Cleaned diesel particulate filter installation	2023	●												
	Clutch calibration	2023					●								
	Cylinder compression, test	2023	●												
	Cylinder deactivation	2023	●												
	Delete clutch overload entries	2023					●								
	EBS trailer control valve, cycle test	2023		●											
	EBS-test additional axle	2023		●											
	EBS-test front axle	2023		●											
	EBS-test rear axle	2023		●											
	Engine oil level check	2023	●												
	Evaluate NOx sensor after catalyst	2023	●												
	Evaluate NOx sensor before catalyst	2023	●												
	Evaluate the engine brake	2023	●												
	Evaluate the injector back leak	2023	●												
	Fuel shut-off valve leak test	2023	●												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Full air, 1 front level sensor, 1 rear level sensor	2023											•		
	Full air, 1 front level sensor, 2 rear level sensors	2023											•		
	Inclination sensor calibration	2023					•								
	Key programming	2023						•							
	Manual entry clutch closing point	2023					•								
	New clutch fitted	2023					•								
	New diesel particulate filter installation	2023	•												
	Next service	2023								•	•				
	Number of programmed keys	2023						•							
	PGN search	2023													
	PGN with source address search	2023													
	Program clutch biting point	2023					•								
	Read configuration data	2023					•								
	Rear air, 1 rear level sensor	2023											•		
	Rear air, 2 rear level sensors	2023											•		
	Rear differential lock solenoid	2023								•					
	Regeneration	2023	•												
	Replace air filter	2023	•												
	Reset of common rail pressure release valve	2023	•												
	Service information	2023													•
	Source address search	2023													
	Test of disengagement behavior of clutch	2023					•								
	Test of water pump	2023	•												
	Unlocking the auxiliary water heater	2023				•									
	Urea dosing system test	2023	•												
	Used clutch fitted	2023					•								
	Variable geometry turbocharger electronic actuator installation	2023	•												
	Vehicle preset max speed	2023													
	Write configuration	2023					•								

EvoBus Chassis

Capacity euro VI	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Intouro euro VI	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
O530 Citaro euro VI	Year model updated	2013-2016	•												
	Erasing of emissions-relevant fault codes	2013-2016	•												
O530 Citaro II	Year model updated	2017-2023	•												
	Erasing of emissions-relevant fault codes	2017-2023	•												
Conecto euro VI	Year model updated	2014-2022	•												
	Erasing of emissions-relevant fault codes	2014-2022	•												
O580 Travego euro VI	Year model updated	2013-2017	•												
	Erasing of emissions-relevant fault codes	2013-2017	•												
OC500 euro VI	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Setra BR 400 euro VI (WKK41(	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Setra BR 400 euro VI (WKK63	Year model updated	2013-2023	•												
	Erasing of emissions-relevant fault codes	2013-2023	•												
Setra BR 500 euro VI	Year model updated	2013-2023	•												
	Erasing of emissions-relevant fault codes	2013-2023	•												
Tourismo euro VI (WEB410)	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Tourismo euro VI (WEB632)	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Integro euro VI	Year model updated	2014-2016	•												
	Erasing of emissions-relevant fault codes	2014-2016	•												

Generic Bus Systems

16-pin J1962 diagnostic socket	Year model updated	All years	•												
	AdBlue dosage test: Large	All years	•												
	AdBlue dosage test: Medium	All years	•												
	AdBlue dosage test: Small	All years	•												
	Erasing of emissions-relevant fault codes	All years	•												
	Reset AdBlue plausibility test	All years	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	All years	•												
	Reset of target values of exhaust gas temp regulator	All years	•												
	Resetting a regeneration block	All years	•												
	Spray test	All years	•												
	Suspected manipulated reset AdBlue	All years	•												
	System pressure build-up, test	All years	•												
All supported systems	Year model updated	All years	•												
	AdBlue dosage test: Large	All years	•												
	AdBlue dosage test: Medium	All years	•												
	AdBlue dosage test: Small	All years	•												
	Erasing of emissions-relevant fault codes	All years	•												
	Reset AdBlue plausibility test	All years	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	All years	•												
	Reset of target values of exhaust gas temp regulator	All years	•												
	Resetting a regeneration block	All years	•												
	Self-adapting parameter reset	All years	•												
	Spray test	All years	•												
	Storing of throttle valve parameters	All years	•												
	Suspected manipulated reset AdBlue	All years	•												
	System pressure build-up, test	All years	•												
30-pin Iveco diagnostic socket	Year model updated	All years	•												
	Self-adapting parameter reset	All years	•												
	Storing of throttle valve parameters	All years	•												

Generic Truck Systems

All supported systems	Year model updated	All years	•												
	AdBlue dosage test: Large	All years	•												
	AdBlue dosage test: Medium	All years	•												
	AdBlue dosage test: Small	All years	•												
	Reset AdBlue plausibility test	All years	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	All years	•												
	Reset of target values of exhaust gas temp regulator	All years	•												
	Resetting a regeneration block	All years	•												
	Self-adapting parameter reset	All years	•												
	Spray test	All years	•												
	Storing of throttle valve parameters	All years	•												
	Suspected manipulated reset AdBlue	All years	•												
	System pressure build-up, test	All years	•												
16-pin J1962 diagnostic socket	Year model updated	All years	•												
	AdBlue dosage test: Large	All years	•												
	AdBlue dosage test: Medium	All years	•												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	AdBlue dosage test: Small	All years	•												
	Reset AdBlue plausibility test	All years	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	All years	•												
	Reset of target values of exhaust gas temp regulator	All years	•												
	Resetting a regeneration block	All years	•												
	Spray test	All years	•												
	Suspected manipulated reset AdBlue	All years	•												
	System pressure build-up, test	All years	•												
30-pin Iveco diagnostic socket	Year model updated	All years	•												
	Self-adapting parameter reset	All years	•												
	Storing of throttle valve parameters	All years	•												

Iveco Bus

Minibus	Year model updated	2019-2023	•	•	•	•	•		•	•	•	•		•	•
	ACM Calibration	2019-2023				•									
	Ad blue tank replacement	2019-2023	•												
	AdBlue dosing module replacement	2019-2021	•												
	AdBlue dosing module replacement (downstream particulate filter)	2019-2023	•												
	AdBlue dosing module replacement (upstream particulate filter)	2019-2023	•												
	AdBlue emptying and replacement	2019-2023	•												
	AdBlue pump module replacement	2019-2023	•												
	AdBlue pump module wiring replacement	2019-2021	•												
	AdBlue quality sensor replacement	2019-2021	•												
	Air flow meter replacement	2019-2023	•												
	Boost pressure sensor replacement	2019-2023	•												
	Brake bleed system ABS/ESP	2019-2023		•											
	Calibration camera	2019-2023													•
	Catalyst replacement	2019-2023	•												
	Change differential pressure sensor	2019-2023	•												
	Current oil quality	2019-2023	•												
	Deactivate service alert system	2019-2023									•				
	EPB Actuators assembly check	2019-2023		•											
	Erase end of travel fault codes	2019-2023		•											
	ESP off, roller bench mode	2019-2023		•											
	Gearbox oil change	2019-2023									•				
	Glow plugs replacement	2019-2023	•												
	Hydraulic system replacement	2019-2021	•												
	Injector code programming	2019-2023	•												
	Lambda sensor replacement	2019-2023	•												
	Longitudinal sensor calibration	2019-2023		•											
	MPROP valve replacement	2019-2023	•												
	Oil change	2019-2023									•				
	Particle filter regeneration	2019-2023	•												
	Particle filter replacement	2019-2023	•												
	Particulate filter replacement	2019-2023	•												
	Rail pressure control valve replacement	2019-2023	•												
	Rail pressure sensor replacement	2019-2023	•												
	Read service parameters	2019-2023									•				
	Replacement of engine crankcase pressure sensor	2019-2023	•												
	Replacement of starter motor	2019-2023	•												
	Replacement of the alternator	2019-2023	•												
	Replacement of the EGR valve	2019-2023	•												
	Replacing the NOX middle sensor of the oxidation catalyst	2019-2023	•												
	Replacing the NOX sensor downstream of the oxidation catalyst	2019-2023	•												
	Replacing the NOX sensor upstream of the oxidation catalyst	2019-2023	•												
	Reset of service message	2019-2023									•				
	SCR (selective catalytic reduction) replacement	2019-2023	•												
	Service history	2019-2023									•				
	Service plan	2019-2023									•				
	Start EPB maintenance mode	2019-2023		•											
	Steering wheel calibration	2019-2023								•					
	Stop EPB maintenance mode	2019-2023		•											
	Throttle valve actuator replacement	2019-2023	•												
	Turbocharger replacement	2019-2023	•												
	Wheel speed sensor calibration	2019-2023		•											

Iveco Trucks

S-way	Year model updated	2019-2022	•	•	•	•	•	•		•	•		•	•	•
	Accelerated clutch adaption	2022					•								
	ACM Calibration	2019-2022				•									
	Air Suspension activation	2019-2022											•		
	Apu test	2022								•					
	Battery replacement	2022								•					
	Brake lining condition	2022		•											
	Calibration camera	2022													•
	Calibration Data	2022													•
	Calibration radar	2022													•
	Clutch calibration	2022					•								
	Clutch replacement (Reset counter for incorrect use of gearbox)	2022						•							
	Cylinder deactivation	2022	•												
	Delete clutch overload entries	2022					•								
	Delta pressure sensor replacement	2022	•												
	Desiccant holder, air dryer, resetting	2022						•							
	Fault memory counter reset	2022	•												
	IBS sensor replacement	2019-2022								•					
	Inclination sensor calibration	2022					•								
	Manual entry clutch closing point	2022					•								
	New clutch fitted	2022					•								
	Oil change	2022									•				
	Particle filter regeneration	2019-2022	•												
	Particulate filter replacement	2022	•												
	Program clutch biting point	2022					•								
	Rail pressure control valve replacement	2022	•												
	Read configuration data	2022					•								
	Regeneration counter reset	2022	•												
	Replacement of engine crankcase pressure sensor	2022	•												
	Replacing the NOX sensor downstream of the oxidation catalyst	2022	•												
	Replacing the NOX sensor upstream of the oxidation catalyst	2022	•												
	Self-adaptive parameters reset	2022	•												
	Test of disengagement behavior of clutch	2022					•								
	Throttle valve learning	2022	•												
	Unlocking the auxiliary water heater	2019-2022				•									
	Used clutch fitted	2022					•								
	Write configuration	2022					•								

Kamaz

54-Series	Year model updated	All years	•												
	Erasing of emissions-relevant fault codes	All years	•												

MAN

TGL [20->]	Year model updated	2020-2023	•	•	•	•	•		•	•	•		•		•
	(Customer specific) Speed limit modification	2020-2023								•					
	4-button keypad	2023								•					
	Activate Brake pad wear symbol and display message	2023		•											
	Activate check lamp brake red/display message	2023		•											
	Activate check lamp yellow/display message	2023		•											
	AdBlue dosage test: Large	2020-2023	•												
	AdBlue dosage test: Medium	2020-2023	•												
	AdBlue dosage test: Small	2020-2023	•												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Automatic adjustment	2023													•
	Brake pad check	2023		•											
	Calibration camera	2023													•
	Calibration Data	2023													•
	Calibration of servomotors	2023				•									
	Calibration radar	2023													•
	Central locking	2023								•					
	Commissioning	2023				•									
	Compression test	2023	•												
	Current oil quality	2023									•				
	Cylinder deactivation	2023	•												
	Delete safety error memory	2023		•											
	Erase SPN 4685	2023	•												
	ESP System Sensors Calibration	2023		•											
	Exchange filter cartridge	2023								•					
	HCI system test	2023	•												
	HCI system test gen 2	2023	•												
	High-pressure test	2023	•												
	Injector programming	2023	•												
	Lambda correction factor	2023	•												
	Level sensor calibration	2023											•		
	LIN addressing of the servomotors	2023				•									
	Line filling confirmation	2023				•									
	Mirror adjustment	2023								•					
	Pressure control module front axle left 1 Bar	2023		•											
	Pressure control module, 2nd axle left 1 bar	2023		•											
	Pressure control module, 2nd axle left 10 bar	2023		•											
	Pressure control module, 2nd axle left 5 bar	2023		•											
	Pressure control module, 2nd axle right 1 bar	2023		•											
	Pressure control module, 2nd axle right 10 bar	2023		•											
	Pressure control module, 2nd axle right 5 bar	2023		•											
	Pressure control module, 3rd axle left 1 bar	2023		•											
	Pressure control module, 3rd axle left 10 bar	2023		•											
	Pressure control module, 3rd axle left 5 bar	2023		•											
	Pressure control module, 3rd axle right 1 bar	2023		•											
	Pressure control module, 3rd axle right 10 bar	2023		•											
	Pressure control module, 3rd axle right 5 bar	2023		•											
	Pressure control module, front axle, left 10 Bar	2023		•											
	Pressure control module, front axle, left 5 Bar	2023		•											
	Pressure control module, front axle, right 1 Bar	2023		•											
	Pressure control module, front axle, right 10 Bar	2023		•											
	Pressure control module, front axle, right 5 Bar	2023		•											
	Pressure limiting valve (DBV) open	2023	•												
	Pressure sensors, Calibration	2023											•		
	Radar sensor offset values	2023													•
	Read injector configuration	2023	•												
	Read service parameters	2023									•				
	Reset AdBlue plausibility	2023	•												
	Reset AdBlue plausibility test	2020-2023	•												
	Reset after oxidation catalyst replacement	2023	•												
	Reset differential pressure sensor	2023	•												
	Reset IDU counter	2023								•					
	Reset learned values of the pressure limiting valve	2023	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2020-2023	•												
	Reset NOx downstream catalytic sensor values	2023	•												
	Reset NOx upstream cat sensor values	2023	•												
	Reset of target values of exhaust gas temp regulator	2020-2023	•												
	Reset parameter; number of interrupted regenerations	2023	•												
	Reset parameter; too frequent regeneration request	2023	•												
	Reset service	2023									•				
	Reset the diesel particulate filter differential pressure sensor learned values	2023	•												
	Reset values after exchanging particulate trap	2023	•												
	Resetting a regeneration block	2020-2023	•												
	Resetting ageing counter for diesel particulate filter	2023	•												
	Resetting ageing counter for SCR1 catalytic converters	2023	•												
	Resetting ageing counter for SCR2 catalytic converters	2023	•												
	Resetting ageing counter for SCR3 catalytic converters	2023	•												
	Resetting aging counter for oxidation catalytic converter	2023	•												
	Resetting catalytic converter blockage detection	2023	•												
	Resetting the values on silencer replacement	2023	•												
	Rev-up test	2023	•												
	Service regeneration	2023	•												
	Slope sensor calibration	2023								•					
	Solenoid valves test	2023											•		
	Spray test	2020-2023	•												
	Suspected manipulated reset AdBlue	2020-2023	•												
	System fill-up	2023				•									
	System pressure build-up, test	2020-2023	•												
	Trip odometer reset	2023								•					
	Vehicle preset max speed	2023													
	Window lifter calibration	2023								•					
	Window Lifter Test	2023								•					
TGM [14-20]	Year model updated	2014-2020	•												
	AdBlue dosage test: Large	2014-2020	•												
	AdBlue dosage test: Medium	2014-2020	•												
	AdBlue dosage test: Small	2014-2020	•												
	Reset AdBlue plausibility test	2014-2020	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2020	•												
	Reset of target values of exhaust gas temp regulator	2014-2020	•												
	Resetting a regeneration block	2014-2020	•												
	Spray test	2014-2020	•												
	Suspected manipulated reset AdBlue	2014-2020	•												
	System pressure build-up, test	2014-2020	•												
TGM [20->]	Year model updated	2020-2023	•	•	•	•	•		•	•	•		•		•
	(Customer specific) Speed limit modification	2020-2023								•					
	4-button keypad	2023								•					
	Activate Brake pad wear symbol and display message	2023		•											
	Activate check lamp brake red/display message	2023		•											
	Activate check lamp yellow/display message	2023		•											
	AdBlue dosage test: Large	2020-2023	•												
	AdBlue dosage test: Medium	2020-2023	•												
	AdBlue dosage test: Small	2020-2023	•												
	Automatic adjustment	2023													•
	Brake pad check	2023		•											
	Calibration camera	2023													•
	Calibration Data	2023													•
	Calibration of servomotors	2023				•									
	Calibration radar	2023													•
	Central locking	2023								•					
	Commissioning	2023				•									
	Compression test	2023	•												
	Current oil quality	2023									•				
	Cylinder deactivation	2023	•												
	Delete safety error memory	2023		•											
	Erase SPN 4685	2023	•												
	ESP System Sensors Calibration	2023		•											
	Exchange filter cartridge	2023								•					
	HCI system test	2023	•												
	HCI system test gen 2	2023	•												
	High-pressure test	2023	•												
	Injector programming	2023	•												
	Lambda correction factor	2023	•												
	Level sensor calibration	2023											•		
	LIN addressing of the servomotors	2023				•									
	Line filling confirmation	2023				•									
	Mirror adjustment	2023								•					

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Pressure control module front axle left 1 Bar	2023		•											
	Pressure control module, 2nd axle left 1 bar	2023		•											
	Pressure control module, 2nd axle left 10 bar	2023		•											
	Pressure control module, 2nd axle left 5 bar	2023		•											
	Pressure control module, 2nd axle right 1 bar	2023		•											
	Pressure control module, 2nd axle right 10 bar	2023		•											
	Pressure control module, 2nd axle right 5 bar	2023		•											
	Pressure control module, 3rd axle left 1 bar	2023		•											
	Pressure control module, 3rd axle left 10 bar	2023		•											
	Pressure control module, 3rd axle left 5 bar	2023		•											
	Pressure control module, 3rd axle right 1 bar	2023		•											
	Pressure control module, 3rd axle right 10 bar	2023		•											
	Pressure control module, 3rd axle right 5 bar	2023		•											
	Pressure control module, front axle, left 10 Bar	2023		•											
	Pressure control module, front axle, left 5 Bar	2023		•											
	Pressure control module, front axle, right 1 Bar	2023		•											
	Pressure control module, front axle, right 10 Bar	2023		•											
	Pressure control module, front axle, right 5 Bar	2023		•											
	Pressure limiting valve (DBV) open	2023	•												
	Pressure sensors, Calibration	2023											•		
	Radar sensor offset values	2023													•
	Read injector configuration	2023	•												
	Read service parameters	2023									•				
	Reset AdBlue plausibility	2023	•												
	Reset AdBlue plausibility test	2020-2023	•												
	Reset after oxidation catalyst replacement	2023	•												
	Reset differential pressure sensor	2023	•												
	Reset IDU counter	2023								•					
	Reset learned values of the pressure limiting valve	2023	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2020-2023	•												
	Reset NOx downstream catalytic sensor values	2023	•												
	Reset NOx upstream cat sensor values	2023	•												
	Reset of target values of exhaust gas temp regulator	2020-2023	•												
	Reset parameter; number of interrupted regenerations	2023	•												
	Reset parameter; too frequent regeneration request	2023	•												
	Reset service	2023									•				
	Reset the diesel particulate filter differential pressure sensor learned values	2023	•												
	Reset values after exchanging particulate trap	2023	•												
	Resetting a regeneration block	2020-2023	•												
	Resetting ageing counter for diesel particulate filter	2023	•												
	Resetting ageing counter for SCR1 catalytic converters	2023	•												
	Resetting ageing counter for SCR2 catalytic converters	2023	•												
	Resetting ageing counter for SCR3 catalytic converters	2023	•												
	Resetting aging counter for oxidation catalytic converter	2023	•												
	Resetting catalytic converter blockage detection	2023	•												
	Resetting the values on silencer replacement	2023	•												
	Rev-up test	2023	•												
	Service regeneration	2023	•												
	Slope sensor calibration	2023								•					
	Solenoid valves test	2023											•		
	Spray test	2020-2023	•												
	Suspected manipulated reset AdBlue	2020-2023	•												
	System fill-up	2023				•									
	System pressure build-up, test	2020-2023	•												
	Trip odometer reset	2023								•					
	Vehicle preset max speed	2023													
	Window lifter calibration	2023								•					
	Window Lifter Test	2023								•					
TGS [14-20]	Year model updated	2014-2020	•												
	AdBlue dosage test: Large	2014-2020	•												
	AdBlue dosage test: Medium	2014-2020	•												
	AdBlue dosage test: Small	2014-2020	•												
	Reset AdBlue plausibility test	2014-2020	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2020	•												
	Reset of target values of exhaust gas temp regulator	2014-2020	•												
	Resetting a regeneration block	2014-2020	•												
	Spray test	2014-2020	•												
	Suspected manipulated reset AdBlue	2014-2020	•												
	System pressure build-up, test	2014-2020	•												
TGS [20->]	Year model updated	2020-2023	•	•	•	•	•		•	•	•		•		•
	(Customer specific) Speed limit modification	2020-2023								•					
	4-button keypad	2023								•					
	Actuator test of clutch	2020-2023					•								
	AdBlue dosage test: Large	2020-2023	•												
	AdBlue dosage test: Medium	2020-2023	•												
	AdBlue dosage test: Small	2020-2023	•												
	Automatic adjustment	2023													•
	Brake pad check	2023		•											
	Calibration camera	2023													•
	Calibration Data	2023													•
	Calibration of servomotors	2023				•									
	Calibration of steering angle sensor	2023		•											
	Calibration radar	2023													•
	Central locking	2023								•					
	Clutch actuator fluid change	2020-2023					•								
	Clutch actuator replacement	2020-2023					•								
	Clutch bleed	2023					•								
	Clutch separation -maximum opening position	2023					•								
	Clutch separation test	2020-2023					•								
	Commissioning	2023				•									
	Compression test	2023	•												
	Current oil quality	2023									•				
	Cylinder deactivation	2023	•												
	Delete safety error memory	2023		•											
	Drain/top up retarder oil	2023					•								
	Enable ZF-CAN	2023					•								
	Erase SPN 4685	2023	•												
	Exchange filter cartridge	2023								•					
	Gear stop values	2023					•								
	Gears, test	2023					•								
	HCI system test	2023	•												
	HCI system test gen 2	2023	•												
	High-pressure test	2023	•												
	Injector programming	2023	•												
	Lambda correction factor	2023	•												
	Level sensor calibration	2023											•		
	LIN addressing of the servomotors	2023				•									
	Line filling confirmation	2023				•									
	Mirror adjustment	2023								•					
	New clutch disc	2023					•								
	New clutch fitted	2020-2023					•								
	New control unit	2020-2023					•								
	New gear shift box fitted	2020-2023					•								
	Position sensor exchanged	2020-2023					•								
	Pressure control modules	2023		•											
	Pressure limiting valve (DBV) open	2023	•												
	Pressure sensors, Calibration	2023											•		
	Program clutch biting point	2023					•								
	Programmed opening position	2023					•								
	Radar sensor offset values	2023													•
	Read injector configuration	2023	•												
	Read service parameters	2023									•				
	Reset AdBlue plausibility	2023	•												
	Reset AdBlue plausibility test	2020-2023	•												
	Reset after oxidation catalyst replacement	2023	•												
	Reset differential pressure sensor	2023	•												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Reset IDU counter	2023								●					
	Reset learned values of the pressure limiting valve	2023	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2020-2023	●												
	Reset NOx downstream catalytic sensor values	2023	●												
	Reset NOx upstream cat sensor values	2023	●												
	Reset of target values of exhaust gas temp regulator	2020-2023	●												
	Reset parameter; number of interrupted regenerations	2023	●												
	Reset parameter; too frequent regeneration request	2023	●												
	Reset service	2023									●				
	Reset the diesel particulate filter differential pressure sensor learned values	2023	●												
	Reset values after exchanging particulate trap	2023	●												
	Resetting a regeneration block	2020-2023	●												
	Resetting ageing counter for diesel particulate filter	2023	●												
	Resetting ageing counter for SCR1 catalytic converters	2023	●												
	Resetting ageing counter for SCR2 catalytic converters	2023	●												
	Resetting ageing counter for SCR3 catalytic converters	2023	●												
	Resetting aging counter for oxidation catalytic converter	2023	●												
	Resetting catalytic converter blockage detection	2023	●												
	Resetting the values on silencer replacement	2023	●												
	Retarder accumulator charging valve	2023					●								
	Retarder proportional valve	2023					●								
	Retarder safety valve	2023					●								
	Retarder switching valve	2023					●								
	Rev-up test	2023	●												
	Screen test	2020-2023								●					
	Service regeneration	2023	●												
	Slope sensor calibration	2023								●					
	Solenoid valve for gate position left	2023					●								
	Solenoid valve for gate position right	2023					●								
	Solenoid valve for high splitter box	2023					●								
	Solenoid valve for low splitter box	2023					●								
	Solenoid valve for shifting backwards	2023					●								
	Solenoid valve for shifting forwards	2023					●								
	Solenoid valve gearbox brake	2023					●								
	Solenoid valve neutral position	2023					●								
	Solenoid valve PTO 1	2023					●								
	Solenoid valve PTO 2	2023					●								
	Solenoid valve range change group fast	2023					●								
	Solenoid valve range change group slow	2023					●								
	Solenoid valves test	2023											●		
	Spray test	2020-2023	●												
	Suspected manipulated reset AdBlue	2020-2023	●												
	System fill-up	2023				●									
	System pressure build-up, test	2020-2023	●												
	Tilt Sensor Calibration	2023					●								
	Trip odometer reset	2023								●					
	Used clutch disc	2023					●								
	Used clutch fitted	2020-2023					●								
	Used control unit fitted	2020-2023					●								
	Vehicle preset max speed	2023													
	Window lifter calibration	2023								●					
	Window Lifter Test	2023								●					
	Yaw Rate Sensor Calibration	2023		●											
TGX [14-20]	Year model updated	2014-2020	●				●								
	Actuator test of clutch	2017-2020					●								
	AdBlue dosage test: Large	2014-2020	●												
	AdBlue dosage test: Medium	2014-2020	●												
	AdBlue dosage test: Small	2014-2020	●												
	Clutch actuator fluid change	2017-2020					●								
	Clutch actuator replacement	2017-2020					●								
	Clutch separation test	2017-2020					●								
	New clutch fitted	2017-2020					●								
	New control unit	2017-2020					●								
	New gear shift box fitted	2017-2020					●								
	Position sensor exchanged	2017-2020					●								
	Reset AdBlue plausibility test	2014-2020	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2020	●												
	Reset of target values of exhaust gas temp regulator	2014-2020	●												
	Resetting a regeneration block	2014-2020	●												
	Spray test	2014-2020	●												
	Suspected manipulated reset AdBlue	2014-2020	●												
	System pressure build-up, test	2014-2020	●												
	Used clutch fitted	2017-2020					●								
	Used control unit fitted	2017-2020					●								
TGX [20->]	Year model updated	2020-2023	●	●	●	●	●		●	●	●		●		●
	(Customer specific) Speed limit modification	2020-2023								●					
	4-button keypad	2023								●					
	Actuator test of clutch	2020-2023					●								
	AdBlue dosage test: Large	2020-2023	●												
	AdBlue dosage test: Medium	2020-2023	●												
	AdBlue dosage test: Small	2020-2023	●												
	Automatic adjustment	2023													●
	Brake pad check	2023		●											
	Calibration camera	2023													●
	Calibration Data	2023													●
	Calibration of servomotors	2023				●									
	Calibration of steering angle sensor	2023		●											
	Calibration radar	2023													●
	Central locking	2023								●					
	Clutch actuator fluid change	2020-2023					●								
	Clutch actuator replacement	2020-2023					●								
	Clutch bleed	2023					●								
	Clutch separation -maximum opening position	2023					●								
	Clutch separation test	2020-2023					●								
	Commissioning	2023				●									
	Compression test	2023	●												
	Current oil quality	2023									●				
	Cylinder deactivation	2023	●												
	Delete safety error memory	2023		●											
	Drain/top up retarder oil	2023					●								
	Enable ZF-CAN	2023					●								
	Erase SPN 4685	2023	●												
	Exchange filter cartridge	2023								●					
	Gear stop values	2023					●								
	Gears, test	2023					●								
	HCI system test	2023	●												
	HCI system test gen 2	2023	●												
	High-pressure test	2023	●												
	Injector programming	2023	●												
	Lambda correction factor	2023	●												
	Level sensor calibration	2023											●		
	LIN addressing of the servomotors	2023				●									
	Line filling confirmation	2023				●									
	Mirror adjustment	2023								●					
	New clutch disc	2023					●								
	New clutch fitted	2020-2023					●								
	New control unit	2020-2023					●								
	New gear shift box fitted	2020-2023					●								
	Position sensor exchanged	2020-2023					●								
	Pressure control modules	2023		●											
	Pressure limiting valve (DBV) open	2023	●												
	Pressure sensors, Calibration	2023											●		
	Program clutch biting point	2023					●								
	Programmed opening position	2023					●								
	Radar sensor offset values	2023													●
	Read injector configuration	2023	●												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Read service parameters	2023									●				
	Reset AdBlue plausibility	2023	●												
	Reset AdBlue plausibility test	2020-2023	●												
	Reset after oxidation catalyst replacement	2023	●												
	Reset differential pressure sensor	2023	●												
	Reset IDU counter	2023								●					
	Reset learned values of the pressure limiting valve	2023	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2020-2023	●												
	Reset NOx downstream catalytic sensor values	2023	●												
	Reset NOx upstream cat sensor values	2023	●												
	Reset of target values of exhaust gas temp regulator	2020-2023	●												
	Reset parameter; number of interrupted regenerations	2023	●												
	Reset parameter; too frequent regeneration request	2023	●												
	Reset service	2023									●				
	Reset the diesel particulate filter differential pressure sensor learned values	2023	●												
	Reset values after exchanging particulate trap	2023	●												
	Resetting a regeneration block	2020-2023	●												
	Resetting ageing counter for diesel particulate filter	2023	●												
	Resetting ageing counter for SCR1 catalytic converters	2023	●												
	Resetting ageing counter for SCR2 catalytic converters	2023	●												
	Resetting ageing counter for SCR3 catalytic converters	2023	●												
	Resetting aging counter for oxidation catalytic converter	2023	●												
	Resetting catalytic converter blockage detection	2023	●												
	Resetting the values on silencer replacement	2023	●												
	Retarder accumulator charging valve	2023					●								
	Retarder proportional valve	2023					●								
	Retarder safety valve	2023					●								
	Retarder switching valve	2023					●								
	Rev-up test	2023	●												
	Screen test	2020-2023								●					
	Service regeneration	2023	●												
	Slope sensor calibration	2023								●					
	Solenoid valve for gate position left	2023					●								
	Solenoid valve for gate position right	2023					●								
	Solenoid valve for high splitter box	2023					●								
	Solenoid valve for low splitter box	2023					●								
	Solenoid valve for shifting backwards	2023					●								
	Solenoid valve for shifting forwards	2023					●								
	Solenoid valve gearbox brake	2023					●								
	Solenoid valve neutral position	2023					●								
	Solenoid valve PTO 1	2023					●								
	Solenoid valve PTO 2	2023					●								
	Solenoid valve range change group fast	2023					●								
	Solenoid valve range change group slow	2023					●								
	Solenoid valves test	2023											●		
	Spray test	2020-2023	●												
	Suspected manipulated reset AdBlue	2020-2023	●												
	System fill-up	2023				●									
	System pressure build-up, test	2020-2023	●												
	Tilt Sensor Calibration	2023					●								
	Trip odometer reset	2023								●					
	Used clutch disc	2023					●								
	Used clutch fitted	2020-2023					●								
	Used control unit fitted	2020-2023					●								
	Vehicle preset max speed	2023													
	Window lifter calibration	2023								●					
	Window Lifter Test	2023								●					
	Yaw Rate Sensor Calibration	2023		●											
TGL [14-20]	Year model updated	2019-2021	●												
	AdBlue dosage test: Large	2019-2021	●												
	AdBlue dosage test: Medium	2019-2021	●												
	AdBlue dosage test: Small	2019-2021	●												
	Reset AdBlue plausibility test	2019-2021	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2019-2021	●												
	Reset of target values of exhaust gas temp regulator	2019-2021	●												
	Resetting a regeneration block	2019-2021	●												
	Spray test	2019-2021	●												
	Suspected manipulated reset AdBlue	2019-2021	●												
	System pressure build-up, test	2019-2021	●												

MAN Bus Chassis

Citybus [14->]	Year model updated	2014-2023	●												
	AdBlue dosage test: Large	2014-2023	●												
	AdBlue dosage test: Medium	2014-2023	●												
	AdBlue dosage test: Small	2014-2023	●												
	Reset AdBlue plausibility test	2014-2023	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2023	●												
	Reset of target values of exhaust gas temp regulator	2014-2023	●												
	Resetting a regeneration block	2014-2023	●												
	Spray test	2014-2023	●												
	Suspected manipulated reset AdBlue	2014-2023	●												
	System pressure build-up, test	2014-2023	●												
Intercitybus [14->]	Year model updated	2014-2023	●												
	AdBlue dosage test: Large	2014-2023	●												
	AdBlue dosage test: Medium	2014-2023	●												
	AdBlue dosage test: Small	2014-2023	●												
	Reset AdBlue plausibility test	2014-2023	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2023	●												
	Reset of target values of exhaust gas temp regulator	2014-2023	●												
	Resetting a regeneration block	2014-2023	●												
	Spray test	2014-2023	●												
	Suspected manipulated reset AdBlue	2014-2023	●												
	System pressure build-up, test	2014-2023	●												
Citybus [Electric]	Year model updated	2021-2023								●					
Touristbus [14->]	Year model updated	2014-2023	●												
	AdBlue dosage test: Large	2014-2023	●												
	AdBlue dosage test: Medium	2014-2023	●												
	AdBlue dosage test: Small	2014-2023	●												
	Reset AdBlue plausibility test	2014-2023	●												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2023	●												
	Reset of target values of exhaust gas temp regulator	2014-2023	●												
	Resetting a regeneration block	2014-2023	●												
	Spray test	2014-2023	●												
	Suspected manipulated reset AdBlue	2014-2023	●												
	System pressure build-up, test	2014-2023	●												

Maz

54-Series	Year model updated	All years	●												
	Erasing of emissions-relevant fault codes	All years	●												
65-Series	Year model updated	All years	●												
	Erasing of emissions-relevant fault codes	All years	●												

Mercedes bus / Setra

Capacity euro VI	Year model updated	2014-2023	●												
	Erasing of emissions-relevant fault codes	2014-2023	●												
Conecto euro VI	Year model updated	2014-2022	●												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Erasing of emissions-relevant fault codes	2014-2022	•												
Integro euro VI	Year model updated	2014-2016	•												
	Erasing of emissions-relevant fault codes	2014-2016	•												
O530 Citaro euro VI	Year model updated	2013-2016	•												
	Erasing of emissions-relevant fault codes	2013-2016	•												
O530 Citaro II	Year model updated	2017-2023	•												
	Erasing of emissions-relevant fault codes	2017-2023	•												
Intouro euro VI	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
O580 Travego euro VI	Year model updated	2013-2017	•												
	Erasing of emissions-relevant fault codes	2013-2017	•												
OC500 euro VI	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Setra BR 400 euro VI (WKK41(	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Setra BR 500 euro VI	Year model updated	2013-2023	•												
	Erasing of emissions-relevant fault codes	2013-2023	•												
Setra BR 400 euro VI (WKK63	Year model updated	2013-2023	•												
	Erasing of emissions-relevant fault codes	2013-2023	•												
Tourismo euro VI (WEB410)	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Tourismo euro VI (WEB632)	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												

Mercedes Truck

Arocs	Year model updated	2013-2020	•			•	•			•					
	Air distribution flap actuator motor	2013-2020				•									
	Blower motor speed level	2013-2020				•									
	Defroster flap actuator motor	2013-2020				•									
	Erasing of emissions-relevant fault codes	2013-2020	•												
	Fresh air / Recirculation flap actuator motor	2013-2020				•									
	Refrigerant compressor magnetic clutch	2013-2020				•									
	Temperature control	2013-2020				•									
	Transport mode	2013-2020								•					
Actros MP IV	Year model updated	2012-2020	•				•			•					
	Erasing of emissions-relevant fault codes	2012-2020	•												
	Transport mode	2012-2020								•					
Atego III	Year model updated	2013-2023	•				•			•					
	Erasing of emissions-relevant fault codes	2013-2023	•												
	Transport mode	2013-2023								•					
Unimog UGE	Year model updated	2013-2023	•				•								
	Erasing of emissions-relevant fault codes	2013-2023	•												
Unimog UHE	Year model updated	2013-2023	•				•								
	Erasing of emissions-relevant fault codes	2013-2023	•												
Econic III	Year model updated	2014-2023	•												
	Erasing of emissions-relevant fault codes	2014-2023	•												
Antos	Year model updated	2013-2020	•				•			•					
	Erasing of emissions-relevant fault codes	2013-2020	•												
	Transport mode	2013-2020								•					
Actros MP V	Year model updated	2019-2023	•				•			•					
	Erasing of emissions-relevant fault codes	2019-2023	•												
	Transport mode	2019-2023								•					
Arocs II	Year model updated	2020-2023	•				•			•					
	Erasing of emissions-relevant fault codes	2020-2023	•												
	Transport mode	2020-2023								•					

Mitsubishi Fuso

Canter (12V)	Year model updated	2018													•
	Calibration by means of test drive	2018													•
	Parameterization of Lane assistant camera	2018													•
	Radar sensor programming	2018													•
	Reactivation of active brake assistance	2018													•
	Reset control unit	2018													•
Canter (24V)	Year model updated	2018													•
	Calibration by means of test drive	2018													•
	Parameterization of Lane assistant camera	2018													•
	Radar sensor programming	2018													•
	Reactivation of active brake assistance	2018													•
	Reset control unit	2018													•

Optare

Versa	Year model updated	2013-2018	•												
	Erasing of emissions-relevant fault codes	2013-2018	•												
Solo	Year model updated	2013-2018	•												
	Erasing of emissions-relevant fault codes	2013-2018	•												
Metrocity	Year model updated	2013-2018	•												
	Erasing of emissions-relevant fault codes	2013-2018	•												
Metrodecker	Year model updated	2014-2018	•												
	Erasing of emissions-relevant fault codes	2014-2018	•												

Scania

S-Series [17->]	Year model updated	2022-2023	•	•			•								
	Checking the clutch	2022-2023		•			•								
	Clutch adaption	2022-2023		•			•								
	Function test of the clutch actuator	2022-2023		•			•								
	Leak test for reductant doser	2022-2023	•												
	Level of clutch disk thickness	2022-2023		•			•								
	Setting total clutch disk thickness	2022-2023		•			•								
	Test for adjusting the accelerometer	2022-2023		•			•								
	Test of Adblue metering amount	2022-2023	•												
R-Series [17->]	Year model updated	2022-2023	•	•			•								
	Checking the clutch	2022-2023		•			•								
	Clutch adaption	2022-2023		•			•								
	Function test of the clutch actuator	2022-2023		•			•								
	Leak test for reductant doser	2022-2023	•												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Level of clutch disk thickness	2022-2023		●			●								
	Setting total clutch disk thickness	2022-2023		●			●								
	Test for adjusting the accelerometer	2022-2023		●			●								
	Test of Adblue metering amount	2022-2023	●												
L-Series [17->]	Year model updated	2022-2023	●	●			●								
	Checking the clutch	2022-2023		●			●								
	Clutch adaption	2022-2023		●			●								
	Function test of the clutch actuator	2022-2023		●			●								
	Leak test for reductant doser	2022-2023	●												
	Level of clutch disk thickness	2022-2023		●			●								
	Setting total clutch disk thickness	2022-2023		●			●								
	Test for adjusting the accelerometer	2022-2023		●			●								
	Test of Adblue metering amount	2022-2023	●												
G-Series [17->]	Year model updated	2022-2023	●	●			●								
	Checking the clutch	2022-2023		●			●								
	Clutch adaption	2022-2023		●			●								
	Function test of the clutch actuator	2022-2023		●			●								
	Leak test for reductant doser	2022-2023	●												
	Level of clutch disk thickness	2022-2023		●			●								
	Setting total clutch disk thickness	2022-2023		●			●								
	Test for adjusting the accelerometer	2022-2023		●			●								
	Test of Adblue metering amount	2022-2023	●												
P-Series [17->]	Year model updated	2022-2023	●	●			●								
	Checking the clutch	2022-2023		●			●								
	Clutch adaption	2022-2023		●			●								
	Function test of the clutch actuator	2022-2023		●			●								
	Leak test for reductant doser	2022-2023	●												
	Level of clutch disk thickness	2022-2023		●			●								
	Setting total clutch disk thickness	2022-2023		●			●								
	Test for adjusting the accelerometer	2022-2023		●			●								
	Test of Adblue metering amount	2022-2023	●												

Scania Bus Chassis

K-Series [22->]	Year model updated	2022-2023	●	●	●		●			●	●		●		●
	(Customer specific) Speed limit modification	2022-2023					●								
	Activate components	2022-2023	●	●						●					
	Activating unit injector solenoid valves	2022-2023	●												
	Adaptation of the throttle	2022-2023	●												
	Auto-adaptive parameters reset	2022-2023		●											
	Base settings for injectors	2022-2023	●												
	Basic setting and calibration of the EGR system	2022-2023	●												
	Basic setting of adaptation of the power take-off	2022-2023	●												
	Basic setting of adaptation values of the mass flow sensor	2022-2023	●												
	Calibrating of all levels	2022-2023											●		
	Calibrating the drive level	2022-2023											●		
	Calibration camera	2022-2023													●
	Calibration Data	2022-2023													●
	Calibration kneeling level	2022-2023											●		
	Calibration of steering angle sensor	2022-2023								●					
	Calibration radar	2022-2023													●
	Check for Internal leaks	2022-2023	●												
	Checking brake wear	2022-2023		●											
	Checking for leaks in the exhaust system	2022-2023	●												
	Checking fuel pressure in the accumulator	2022-2023	●												
	Checking reductant tank´s level sensor	2022-2023	●												
	Checking the fuel metering valve	2022-2023	●												
	Clutch adaption	2022-2023					●								
	Compression test	2022-2023	●												
	Configuration pressure sensor	2022-2023								●					
	Current vehicle speed	2022-2023													
	Cylinder Balancing	2022-2023	●												
	Cylinder deactivation	2022-2023	●												
	Cylinder output test	2022-2023	●												
	Data reset for soot and ash	2022-2023	●												
	Default setting for adaptation of the charge air pressure sensor and exhaust gas pressure sensor	2022-2023	●												
	Default setting for injected reductant volume adaptation	2022-2023	●												
	Diesel particulate filter regeneration	2022-2023	●												
	Disengagement of manual gear changing limitation	2022-2023					●								
	Fuel leak test	2022-2023	●												
	Function test of the clutch actuator	2022-2023					●								
	Injector programming	2022-2023	●												
	Intake manifold pressure adaption	2022-2023	●												
	Leak test for reductant doser	2022-2023	●												
	Low reductant consumption check	2022-2023	●												
	Mileage from Coordinator-ECU	2022-2023													
	Read data from ECU and save data to file	2022-2023								●					
	Read service parameters	2022-2023									●				
	Reducing the fuel pressure	2022-2023	●												
	Reductant thawing test	2022-2023	●												
	Reset differential pressure sensor	2022-2023	●												
	Reset intake manifold pressure adaption	2022-2023	●												
	Reset the service interval	2022-2023									●				
	Reset the values when renewing the desiccant container	2022-2023								●					
	Resetting fuel adaption	2022-2023	●												
	Setting total clutch disk thickness	2022-2023					●								
	System overview	2022-2023	●												
	Test for adjusting the accelerometer	2022-2023					●								
	Test of Adblue metering amount	2022-2023	●												
	Vehicle preset max speed	2022-2023													
	Venting the SCR system	2022-2023	●												
	Write data to ECU from file	2022-2023								●					
	Yaw Rate Sensor Calibration	2022-2023		●											
N-Series [14->]	Year model updated	2021	●	●	●		●			●	●		●		●
	(Customer specific) Speed limit modification	2021	●												
	Activate components	2021	●												
	Activating unit injector solenoid valves	2021	●												
	Adaptation of the throttle	2021	●												
	Auto-adaptive parameters reset	2021		●											
	Base settings for injectors	2021	●												
	Basic setting and calibration of the EGR system	2021	●												
	Basic setting of adaptation of the power take-off	2021	●												
	Basic setting of adaptation values of the mass flow sensor	2021	●												
	Calibrating of all levels	2021											●		
	Calibrating the drive level	2021											●		
	Calibration camera	2021													●
	Calibration Data	2021													●
	Calibration kneeling level	2021											●		
	Calibration of steering angle sensor	2021		●											
	Calibration radar	2021													●
	Check for Internal leaks	2021	●												
	Checking fuel pressure in the accumulator	2021	●												
	Checking fuel supply pressure	2021	●												
	Checking reductant tank´s level sensor	2021	●												
	Clutch adaption	2021		●			●								
	Compression test	2021	●												
	Condition test on the variable geometry turbocharger	2021	●												
	Current vehicle speed	2021													
	Cylinder Balancing	2021	●												
	Cylinder deactivation	2021	●												
	Cylinder output test	2021	●												
	Data reset for soot and ash	2021	●												
	Default setting for injected reductant volume adaptation	2021	●												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Diesel particulate filter regeneration	2021	•												
	Fluid change and bleeding the clutch actuator	2021		•			•								
	Function test EGR	2021	•												
	Function test of the clutch actuator	2021		•			•								
	Function test SCR	2021	•												
	Info about adjusting the K-factor in the Coordinator	2021								•					
	Injector programming	2021	•												
	Intake manifold pressure adaption	2021	•												
	Leak test for reductant doser	2021	•												
	Low reductant consumption check	2021	•												
	Mileage from Coordinator-ECU	2021													
	Proportional valve for exhaust brake	2021	•												
	PWM signal to alternator	2021	•												
	Read data from ECU and save data to file	2021								•					
	Read service parameters	2021									•				
	Reading calibration values for variable geometry turbocharger	2021	•												
	Reducing the fuel pressure	2021	•												
	Reductant doser	2021	•												
	Reductant pressure sensor check	2021	•												
	Reductant thawing test	2021	•												
	Requested position for the EGR valve	2021	•												
	Reset differential pressure sensor	2021	•												
	Reset intake manifold pressure adaption	2021	•												
	Reset the service interval	2021									•				
	Resetting air meter	2021								•					
	Resetting EGR data	2021	•												
	Resetting fuel adaption	2021	•												
	SCR system test	2021	•												
	Setting total clutch disk thickness	2021		•			•								
	System overview	2021	•												
	Test of Adblue metering amount	2021	•												
	Urea dosing system test	2021	•												
	Vehicle preset max speed	2021	•												
	Write data to ECU from file	2021								•					
	Yaw Rate Sensor Calibration	2021		•											
C-Series [22->]	Year model updated	2022-2023	•	•	•		•			•	•		•		•
	(Customer specific) Speed limit modification	2022-2023					•								
	Activate components	2022-2023	•	•						•					
	Activating unit injector solenoid valves	2022-2023	•												
	Adaptation of the throttle	2022-2023	•												
	Auto-adaptive parameters reset	2022-2023		•											
	Base settings for injectors	2022-2023	•												
	Basic setting and calibration of the EGR system	2022-2023	•												
	Basic setting of adaptation of the power take-off	2022-2023	•												
	Basic setting of adaptation values of the mass flow sensor	2022-2023	•												
	Calibrating of all levels	2022-2023											•		
	Calibrating the drive level	2022-2023											•		
	Calibration camera	2022-2023													•
	Calibration Data	2022-2023													•
	Calibration kneeling level	2022-2023											•		
	Calibration of steering angle sensor	2022-2023								•					
	Calibration radar	2022-2023													•
	Check for Internal leaks	2022-2023	•												
	Checking brake wear	2022-2023		•											
	Checking for leaks in the exhaust system	2022-2023	•												
	Checking fuel pressure in the accumulator	2022-2023	•												
	Checking reductant tank´s level sensor	2022-2023	•												
	Checking the fuel metering valve	2022-2023	•												
	Clutch adaption	2022-2023					•								
	Compression test	2022-2023	•												
	Configuration pressure sensor	2022-2023								•					
	Current vehicle speed	2022-2023													
	Cylinder Balancing	2022-2023	•												
	Cylinder deactivation	2022-2023	•												
	Cylinder output test	2022-2023	•												
	Data reset for soot and ash	2022-2023	•												
	Default setting for adaptation of the charge air pressure sensor and exhaust gas pressure sensor	2022-2023	•												
	Default setting for injected reductant volume adaptation	2022-2023	•												
	Diesel particulate filter regeneration	2022-2023	•												
	Disengagement of manual gear changing limitation	2022-2023					•								
	Fuel leak test	2022-2023	•												
	Function test of the clutch actuator	2022-2023					•								
	Injector programming	2022-2023	•												
	Intake manifold pressure adaption	2022-2023	•												
	Leak test for reductant doser	2022-2023	•												
	Low reductant consumption check	2022-2023	•												
	Mileage from Coordinator-ECU	2022-2023													
	Read data from ECU and save data to file	2022-2023								•					
	Read service parameters	2022-2023									•				
	Reducing the fuel pressure	2022-2023	•												
	Reductant thawing test	2022-2023	•												
	Reset differential pressure sensor	2022-2023	•												
	Reset intake manifold pressure adaption	2022-2023	•												
	Reset the service interval	2022-2023									•				
	Reset the values when renewing the desiccant container	2022-2023								•					
	Resetting fuel adaption	2022-2023	•												
	Setting total clutch disk thickness	2022-2023					•								
	System overview	2022-2023	•												
	Test for adjusting the accelerometer	2022-2023					•								
	Test of Adblue metering amount	2022-2023	•												
	Vehicle preset max speed	2022-2023													
	Venting the SCR system	2022-2023	•												
	Write data to ECU from file	2022-2023								•					
	Yaw Rate Sensor Calibration	2022-2023		•											
Citywide [22->]	Year model updated	2022-2023	•	•	•		•			•	•		•		•
	(Customer specific) Speed limit modification	2022-2023					•								
	Activate components	2022-2023	•	•						•					
	Activating unit injector solenoid valves	2022-2023	•												
	Adaptation of the throttle	2022-2023	•												
	Auto-adaptive parameters reset	2022-2023		•											
	Base settings for injectors	2022-2023	•												
	Basic setting and calibration of the EGR system	2022-2023	•												
	Basic setting of adaptation of the power take-off	2022-2023	•												
	Basic setting of adaptation values of the mass flow sensor	2022-2023	•												
	Calibrating of all levels	2022-2023											•		
	Calibrating the drive level	2022-2023											•		
	Calibration camera	2022-2023													•
	Calibration Data	2022-2023													•
	Calibration kneeling level	2022-2023											•		
	Calibration of steering angle sensor	2022-2023								•					
	Calibration radar	2022-2023													•
	Check for Internal leaks	2022-2023	•												
	Checking brake wear	2022-2023		•											
	Checking for leaks in the exhaust system	2022-2023	•												
	Checking fuel pressure in the accumulator	2022-2023	•												
	Checking reductant tank´s level sensor	2022-2023	•												
	Checking the fuel metering valve	2022-2023	•												
	Clutch adaption	2022-2023					•								
	Compression test	2022-2023	•												
	Configuration pressure sensor	2022-2023								•					
	Current vehicle speed	2022-2023													
	Cylinder Balancing	2022-2023	•												
	Cylinder deactivation	2022-2023	•												
	Cylinder output test	2022-2023	•												
	Data reset for soot and ash	2022-2023	•												
	Default setting for adaptation of the charge air pressure sensor and exhaust gas pressure sensor	2022-2023	•												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Default setting for injected reductant volume adaptation	2022-2023	•												
	Diesel particulate filter regeneration	2022-2023	•												
	Disengagement of manual gear changing limitation	2022-2023					•								
	Fuel leak test	2022-2023	•												
	Function test of the clutch actuator	2022-2023					•								
	Injector programming	2022-2023	•												
	Intake manifold pressure adaption	2022-2023	•												
	Leak test for reductant doser	2022-2023	•												
	Low reductant consumption check	2022-2023	•												
	Mileage from Coordinator-ECU	2022-2023													
	Read data from ECU and save data to file	2022-2023								•					
	Read service parameters	2022-2023									•				
	Reducing the fuel pressure	2022-2023	•												
	Reductant thawing test	2022-2023	•												
	Reset differential pressure sensor	2022-2023	•												
	Reset intake manifold pressure adaption	2022-2023	•												
	Reset the service interval	2022-2023									•				
	Reset the values when renewing the desiccant container	2022-2023								•					
	Resetting fuel adaption	2022-2023	•												
	Setting total clutch disk thickness	2022-2023					•								
	System overview	2022-2023	•												
	Test for adjusting the accelerometer	2022-2023					•								
	Test of Adblue metering amount	2022-2023	•												
	Vehicle preset max speed	2022-2023													
	Venting the SCR system	2022-2023	•												
	Write data to ECU from file	2022-2023								•					
	Yaw Rate Sensor Calibration	2022-2023		•											
Touring HD [22->]	Year model updated	2022-2023	•	•	•		•			•	•		•		•
	(Customer specific) Speed limit modification	2022-2023					•								
	Activate components	2022-2023	•	•						•					
	Activating unit injector solenoid valves	2022-2023	•												
	Auto-adaptive parameters reset	2022-2023		•											
	Base settings for injectors	2022-2023	•												
	Basic setting of adaptation of the power take-off	2022-2023	•												
	Basic setting of adaptation values of the mass flow sensor	2022-2023	•												
	Calibrating of all levels	2022-2023											•		
	Calibrating the drive level	2022-2023											•		
	Calibration camera	2022-2023													•
	Calibration Data	2022-2023													•
	Calibration kneeling level	2022-2023											•		
	Calibration of steering angle sensor	2022-2023								•					
	Calibration radar	2022-2023													•
	Checking brake wear	2022-2023		•											
	Checking for leaks in the exhaust system	2022-2023	•												
	Checking fuel pressure in the accumulator	2022-2023	•												
	Checking reductant tank´s level sensor	2022-2023	•												
	Checking the fuel metering valve	2022-2023	•												
	Clutch adaption	2022-2023					•								
	Compression test	2022-2023	•												
	Configuration pressure sensor	2022-2023								•					
	Current vehicle speed	2022-2023													
	Cylinder Balancing	2022-2023	•												
	Cylinder deactivation	2022-2023	•												
	Cylinder output test	2022-2023	•												
	Data reset for soot and ash	2022-2023	•												
	Default setting for adaptation of the charge air pressure sensor and exhaust gas pressure sensor	2022-2023	•												
	Default setting for injected reductant volume adaptation	2022-2023	•												
	Diesel particulate filter regeneration	2022-2023	•												
	Disengagement of manual gear changing limitation	2022-2023					•								
	Fuel leak test	2022-2023	•												
	Function test of the clutch actuator	2022-2023					•								
	Injector programming	2022-2023	•												
	Leak test for reductant doser	2022-2023	•												
	Low reductant consumption check	2022-2023	•												
	Mileage from Coordinator-ECU	2022-2023													
	Read data from ECU and save data to file	2022-2023								•					
	Read service parameters	2022-2023									•				
	Reducing the fuel pressure	2022-2023	•												
	Reductant thawing test	2022-2023	•												
	Reset differential pressure sensor	2022-2023	•												
	Reset the service interval	2022-2023									•				
	Reset the values when renewing the desiccant container	2022-2023								•					
	Setting total clutch disk thickness	2022-2023					•								
	System overview	2022-2023	•												
	Test for adjusting the accelerometer	2022-2023					•								
	Test of Adblue metering amount	2022-2023	•												
	Vehicle preset max speed	2022-2023													
	Venting the SCR system	2022-2023	•												
	Write data to ECU from file	2022-2023								•					
	Yaw Rate Sensor Calibration	2022-2023		•											
Interlink [22->]	Year model updated	2022-2023	•	•	•		•			•	•		•		•
	(Customer specific) Speed limit modification	2022-2023					•								
	Activate components	2022-2023	•	•						•					
	Activating unit injector solenoid valves	2022-2023	•												
	Adaptation of the throttle	2022-2023	•												
	Auto-adaptive parameters reset	2022-2023		•											
	Base settings for injectors	2022-2023	•												
	Basic setting and calibration of the EGR system	2022-2023	•												
	Basic setting of adaptation of the power take-off	2022-2023	•												
	Basic setting of adaptation values of the mass flow sensor	2022-2023	•												
	Calibrating of all levels	2022-2023											•		
	Calibrating the drive level	2022-2023											•		
	Calibration camera	2022-2023													•
	Calibration Data	2022-2023													•
	Calibration kneeling level	2022-2023											•		
	Calibration of steering angle sensor	2022-2023								•					
	Calibration radar	2022-2023													•
	Check for Internal leaks	2022-2023	•												
	Checking brake wear	2022-2023		•											
	Checking for leaks in the exhaust system	2022-2023	•												
	Checking fuel pressure in the accumulator	2022-2023	•												
	Checking reductant tank´s level sensor	2022-2023	•												
	Checking the fuel metering valve	2022-2023	•												
	Clutch adaption	2022-2023					•								
	Compression test	2022-2023	•												
	Configuration pressure sensor	2022-2023								•					
	Current vehicle speed	2022-2023													
	Cylinder Balancing	2022-2023	•												
	Cylinder deactivation	2022-2023	•												
	Cylinder output test	2022-2023	•												
	Data reset for soot and ash	2022-2023	•												
	Default setting for adaptation of the charge air pressure sensor and exhaust gas pressure sensor	2022-2023	•												
	Default setting for injected reductant volume adaptation	2022-2023	•												
	Diesel particulate filter regeneration	2022-2023	•												
	Disengagement of manual gear changing limitation	2022-2023					•								
	Fuel leak test	2022-2023	•												
	Function test of the clutch actuator	2022-2023					•								
	Injector programming	2022-2023	•												
	Intake manifold pressure adaption	2022-2023	•												
	Leak test for reductant doser	2022-2023	•												
	Low reductant consumption check	2022-2023	•												
	Mileage from Coordinator-ECU	2022-2023													
	Read data from ECU and save data to file	2022-2023								•					
	Read service parameters	2022-2023									•				
	Reducing the fuel pressure	2022-2023	•												
	Reductant thawing test	2022-2023	•												

autocom

			Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS	ADAS
	Reset differential pressure sensor	2022-2023	•		•	•	•	•	•	•	•	•	•	•	•
	Reset intake manifold pressure adaption	2022-2023	•												
	Reset the service interval	2022-2023									•				
	Reset the values when renewing the desiccant container	2022-2023								•					
	Resetting fuel adaption	2022-2023	•												
	Setting total clutch disk thickness	2022-2023					•								
	System overview	2022-2023	•												
	Test for adjusting the accelerometer	2022-2023					•								
	Test of Adblue metering amount	2022-2023	•												
	Vehicle preset max speed	2022-2023													
	Venting the SCR system	2022-2023	•												
	Write data to ECU from file	2022-2023								•					
	Yaw Rate Sensor Calibration	2022-2023		•											

Temsa

MD7 Euro 6	Year model updated	2019-2021	•												
	Compression test	2019-2021	•												

MD9 Euro 6	Year model updated	2014-2021	•												
	AdBlue dosage test: Large	2014-2021	•												
	AdBlue dosage test: Medium	2014-2021	•												
	AdBlue dosage test: Small	2014-2021	•												
	Reset AdBlue plausibility test	2014-2021	•												
	Reset monitoring for excessively frequent detection of the WWH-OBD diagnostic memory	2014-2021	•												
	Reset of target values of exhaust gas temp regulator	2014-2021	•												
	Resetting a regeneration block	2014-2021	•												
	Spray test	2014-2021	•												
	Suspected manipulated reset AdBlue	2014-2021	•												
	System pressure build-up, test	2014-2021	•												