



2026 Cleveland Swan-Tyee Intertie Brushing Project

ADDENDUM NO. 1

Date: February 23, 2026
Bids Due: March 5, 2026 @ 4:00 p.m. AKST (no change)
Pages: One (1) total

- Notes:**
1. Bidders must acknowledge receipt of addenda in Section 5 of Attachment No. 1 to the Request for Proposals (RFP) titled "Contractor's Bid and Addendum Acknowledgement Form".
 2. This addendum provides additional and/or modified information to the Project RFP and associated documents. This addendum forms a part of the Contract Documents. This addendum is being transmitted by e-mail to all pre-registered bidders and posted on SEAPA's website at <https://www.seapahydro.org/opportunities/bids-projects>
 3. No hard copy will be sent.
 4. All other terms and conditions of the original RFP and associated documents are unchanged.
-

INQUIRIES / CLARIFICATIONS:

1. Bonds. Page 13 of the proposal says "None required". Question 3 of the financial questionnaire asks if we have made arrangements with a surety company. Will going through the trouble and expense of getting bonded shed a more favorable light on a bidder?

SEAPA RESPONSE:

No. Bidders shall mark "Not applicable" in the response section of Question 3 in Attachment No. 7 to the RFP (Contractor's General Questionnaire).

2. What are the dimensions of the nice green and tan helipads seen at the site?

SEAPA RESPONSE:

12' x 12'.

3. Drawings pages show multiple new pads to be put in but it seems at least some are already there. Would it be possible to get a latitude and longitude for existing helipads?

SEAPA RESPONSE:

No, latitude and longitude coordinates are not available for existing helipads.

4. Drawings show a trail to cut for proposed new pad between #199 - #200. Please confirm this pad is not built yet and still needs to be cut.

SEAPA RESPONSE:

Bidders shall assume it still needs to be cut and include the cost of cutting in their bids accordingly.

5. Confirm 208-209-210-211 is not part of the area to be cut as those spans are not shown on the ROW table of areas to be cut.

SEAPA RESPONSE:

That is correct. These spans are not part of the area to be brushed.

End of Addendum No. 1
