

SAFETY ALERT

214 Oxy-Acetylene Torch Event

INCIDENT OVERVIEW

INCIDENT OVERVIEW

PIM Contractor had used a flint igniter to light an oxyacetylene torch. As there was only one igniter, the worker has placed the lit torch on top of the acetylene bottle and then walked over to the other worker to give them the ignitor. As they did this the torch as fallen off and ended up resting against the acetylene bottle resulting in a burn area to the side of the bottle. (Photo attached)

How are the people involved?

There were no persons injured in this event

What immediate actions were taken?

- The site supervisor has noticed the torch and run over to remove the torch, turned off the gas and disconnect the hose from the bottle
- The bottle was removed to outside and then vented to reduce pressure from the heating

What further actions are required?

Refresh all employees on the hazards involved in gas cutting equipment.

Purchase additional flint ignitors

Review the Sub-Contractor engagement and on boarding process



WHAT CAN BE DONE DIFFERENTLY TO PREVENT A SIMILAR INCIDENT FROM **OCCURRING?**



Co-worker could have walked over to pick up the flint ignitor



Procedure not followed – acetylene torches are very dangerous and should never be left lit and unattended



Flint ignitor was the correct tool though one should be supplied for each gas kit

Torch should not have been left on and unattended

For more information regarding this incident please contact:

National HSEQ Manager:	Michael Kelly
Contact Number:	0408 219 426
Date of Issue:	28th of October 2019

LESSONS

- ► All tools and equipment have inherent risk which must be understood by the person who is using the equipment. Safe methods of handling, using and storing must be understood and followed at all times.
- ▶ Tools and equipment must never be left energised and unattended. Energised equipment may injure persons or do damage to other property or equipment.
- ▶ It's good practice to remain aware of the work environment and to take immediate action to correct any unsafe acts or conditions

Report all incidents and near misses

Please display on Safety Noticeboards and raise this matter at the next Toolbox Talk or Safety Meeting.

Doc No: PRG GHSE F011 Version: 2.0 Review Date: 16/08/2024 Proc. Ref: PRG GHSE P013 Issue Date: 16/08/2019 Page 1 of 1 This document is uncontrolled when printed.

