

Notification Number

17

Safety Alert

Health Alert

Best Practice Advice

Innovation Advice

Environmental Alert

Environmental Focus

Date: 4th September 2024

Focus Group: Mobile plant R&M

Region: All

Topic: Safe inspection where entrapment hazards exist

Background

- One of the most frequent repairs undertaken in our forest operations is replacing leaking or ruptured hydraulic hoses
- The positioning of some hydraulic hoses is awkward and its sometimes difficult to see where a leak is. The problem can be identified by function testing, but sometimes the exact hose needs to be identified by getting close and looking for the leak.
- The engine needs to be running to work the functions for a service person to inspect and find the leak. In some situations, this can put a person in a compromised position and expose them to entrapment risks.
- The RMF SSoW talks about a zero energy state before repairs can take place and continues to require all lockout devices to be installed and a secondary form of support, where appropriate, before any repairs can take place.
- The problem is that the fault needs to be identified before all these safety precautions can be implemented.

Best Practice

- Telescopic inspection mirrors or commonly known as a mechanics mirror was first created during the Great Depression in 1935. They went on to play a pivotal role in assembly plants worldwide during the Second World War. Today they are commonplace in workshops and fabrication plants worldwide.
- They are cheap and provide an effective means of gaining vision in hard to reach places while remaining at a safe distance.
- We recommend that this tool should be available in everyone's toolbox when performing repair and maintenance on our forestry sites.
- Once a fault is identified, the RMF SSoW guidance along with any manufacturer or supplier guidance and precautions MUST be followed to safely perform the work. Your risk assessment and controls will further support this process.



SCA

**SCA Telescopic Inspection Mirror
50mm**

\$11.99

★★★★★ 4.5 (36) Write a review

Item No. 107245

1 ▾

Add To Cart

♥ Add to my Wishlist

Tools > Pick Up & Inspection > Inspection & Pick Up Mirrors > Kinchrome Inspection Mirror with LED Light-720mm (Each)

EMAIL US PRINT



Kinchrome Inspection Mirror with LED Light-720mm (Each)

Code : 440421 AVAILABILITY: Expected Dispatch 20-09-2024

\$53.19 \$61.17 incl. GST

QTY: - 1 + Add to Cart

PRODUCT DESCRIPTION

Home / Tools / Hand Tools / Plumbing Tools / Inspection Mirror Telescopic 50mm Round 200-400mm FGIM50



Haron Inspection Mirror Telescopic 50mm Round 200-400mm FGIM50

SKU: 7642813 | Part Code: FGIM50

\$53.99 EA

- 1 + ADD TO CART

Select your nearest store For delivery options and stock availability

Product Details Returns Contact Us Trade - Check your price

For access to our safety alert database scan the QR Code below from your mobile phone:



For access from a desktop computer, follow the link below:

[RMF - Workplace Notifications](#)

Disclaimer: Information in this notification is based on initial observations or conclusions. Because some events may be subject to ongoing investigation, details may be subject to change.