



Richard Crookes Constructions

The Art Gallery of NSW
Sydney Modern Development

Noise and Vibration Monitoring Results

DECEMBER


White Noise Acoustics
303, 74 Pitt Street,
Sydney NSW 2000

ABN: 35 632 449 122


The information in this document is subject to copyright and is the property of White Noise Acoustics. This document shall be returned if demanded. This document and the information contained within this document shall not be reproduced, copied, or communicated to another party other than for that with relation to the relevant inquiry or project without written permission from White Noise Acoustics.

7 Appendix B – Logger Location 1 – Monitor 7543


M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance



M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




M7543 7543 - White Noise Acoustics @ 7543 - Monitor 6 - Compliance




8 Appendix C –Logger Location 2 – Monitor M7542


M7542 7542 - White Noise Acoustics @ 7542 - Monitor 5 - Compliance




M7542 7542 - White Noise Acoustics @ 7542 - Monitor 5 - Compliance




M7542 7542 - White Noise Acoustics @ 7542 - Monitor 5 - Compliance



M7542 7542 - White Noise Acoustics @ 7542 - Monitor 5 - Compliance




M7542 7542 - White Noise Acoustics @ 7542 - Monitor 5 - Compliance




9 Appendix D –Logger Location 3 – Monitor M7541


M7541 7541 - White Noise Acoustics @ 7541 - Monitor 4 - Compliance




M7541 7541 - White Noise Acoustics @ 7541 - Monitor 4 - Compliance




M7541 7541 - White Noise Acoustics @ 7541 - Monitor 4 - Compliance




M7541 7541 - White Noise Acoustics @ 7541 - Monitor 4 - Compliance



M7541 7541 - White Noise Acoustics @ 7541 - Monitor 4 - Compliance




M7541 7541 - White Noise Acoustics @ 7541 - Monitor 4 - Compliance




10 Appendix E –Logger Location 4 – Monitor M7517


M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance




M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance




M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance




M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance




M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance




M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance



M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance



M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance



M7517 7517 - White Noise Acoustics @ 7517 - Monitor 3 - Compliance

