

SAFETY ALERT

SA-228 – Security of Hired Plant

INCIDENT OVERVIEW

A hired scissor lift similar to the one shown below, was used to wash high elevations and when the work was completed, the foreman rang the hire company and requested the machine be collected. The workers then left the keys on top of the fuel tank, closed the engine cowling and left the site.

An error however occurred within the Hire company systems and the message to pick-up the scissor lift never made it to the collection driver.

The scissor lift sat for four days until the manager of local café that was opposite to the worksite, saw children interfering with it by taking it for a spin on the nearby lawn. After confronting the children, they ran off and the local Council where advised and arrangements were made to collect the machine.

Leaving the keys hidden on the machine was standard industry practice however this event highlighted that this wasn't safe nor secure.

The hire company acknowledged the error with their systems and have since provided an additional set of keys that the workers can take when they leave site. The hire company will instead use a master set of keys to collect the machine.

No photos of the machine were taken at the time it was being driven by the children however the marks on the grass afterwards show the path the children took.





The lawn shows the result of unauthorised use of the machine.

WHAT CAN BE DONE DIFFERENTLY TO PREVENT A SIMILAR INCIDENT FROM OCCURRING?



Responsibility towards the safe use of the hired plant also includes ensuring it is left in a secure state until the Hire Company collects it.



Removal of the keys, use of a lock box or other similar security measures are options that could be taken. Hiding the keys on the machine does not guarantee it will be secure.

For more information regarding this incident please contact:

HSE Representative:	Tony Higgison
Contact Number:	+64 21447418
Date of Issue:	27 th August 2020

Report all incidents and near misses

Please display on Safety Noticeboards and raise this matter at the next Toolbox Talk or Safety Meeting.

 Doc No: PRG GHSE F011
 Version: 2.0
 Issue Date: 16/08/2019
 Review Date: 16/08/2024
 Proc. Ref: PRG GHSE P013

