

## SAFETY ALER

Date: 28/4/2021

**Mechanical** 

**Topic: CG 470 Hand brake** 

**Issued by: Handles** Facts: On a wet Friday afternoon at Silver peaks, forest (Otago) the operator was loading the unit with logs when the truck and trailer took off down a hill hitting a parked ute before

coming to rest in a tree, around 75 metres.

Upon investigation, it appears that the handbrake itself was not functioning properly by not locking in, as it should. When the driver got a jacket out of the back bunk, it caught the lever causing the lever to drop. The driver was in the safe zone, and there was no injuries, truck was a total loss.

The driver had only been on the unit for 3 days and had not noticed the fault.

Mechanical inspection of the mechanism found it did lock in properly as other similar age CG470 models do.





**Risk Awareness:** 

## Safe Behaviour:

- Please check hand brake lever is locking into position before exiting vehicle
- Be careful when getting PPE or items from the back bunk in case they get snagged
- Making sure handbrake levers a checked as part of servicing and maintenance.
- Making sure faults are recorded on Pre-Checks sheets

For Site Manager use (print document and then complete):	
This safety alert is relevant to my site?	Yes / No
If yes,	
This safety alert has been discussed with employees and contractors	
• I have placed this safety alert on the site safety notice board	
Site Manager: C	Date: